






Terrebonne Survey and Removal Status

-  Survey area (119 snm)
-  100 % side-scan sonar survey complete
-  200 % side-scan sonar survey complete*
-  Sonar survey data available
-  Removal operations complete

* Target data is being processed and currently not available